


10:	From: Pu	<u>iblic works/Road</u>	<u>Ops</u>
Fax:	Pages:	1	
Phone:	Date:	9/10/2013	
E-Mail:			
TREE REMOVAL REQU	<u>EST</u>		
Road Name: Twin Ponds Rd Nearest City: Umatilla Address: N/A Section 18 Township: 18 Description of Tree: oak Location of Tree: Approx 650 Size of tree (s): Three, growin Grind Stump? yes Remove 9 If trim what class? Class 1 Power Lines or other hazards Sod? Yes No Comments: Marked with oran recently, and the remainder is	8 Range: 27 ft East of Skyling out of same Stump? Class 2 involved? Yes Type of	ne stump: 20", 21", 2 Class 3 \ No \ sod Needed: pe. Tree is green,	Stump stee 66
Questions concerning tree size(s) shall or designee prior to the performance of paid in accordance with the terms and below.	be addressed and a f the work. Any wo	greed upon in writing by erk performed without agre	either the Project Manager eement by all parties shall be
Approved by: County Represe	<u>Date:</u> ntative		
Work Completed and OK	to Pay: Yes	No No	
Inspected by:		Date:	
Invoice #			


Request Details Report

Associated Work Order Request Number Observed Date/Time MA3-18427-WO 9/6/13 3:30:P MA3-11353-R Citizen Information Name Kevin Williamson Phone (352) 638-0583 Ext. **Alternate Phone** Address **Email Address** Not Provided (0000) Organization Requestor Contact Tree Removal Issue and Location Issue Activity Map Page SEC TWN RNG RDS Storm Debris Pick Up **Address Number** Route Twin Ponds Rd (7676) Intersect Route Details Tree fell across the road. **Notes** History 9/9/2013 Citizen requests that we remove the other 3 parts of the tree that Wall, Treeva are still standing. Resolution ___ Request Response Date 09/06/2013

Time Arrived_____

Time Departed_____







Lake County GIS

Click here to change page title



#	Alt Key	Owner	Parcel Address	Owner Address	Tools
				L	