

To: Merrell's Grade-All	From: Public Wor	ks Road Ops
Fax: (407) 892-0808	Phone: <u>352-343-6</u>	6439
Phone:407-892-4700	Pages: 1	
Re: 10-0610 Ditch Digging/Cleaning		Date: 5/29/2014
WORK REQUEST		
This is a Work Order per the site visit conducted with Merrill's Grade-all and the Maintenance Area Supervisor.		
Grade-All work per hour (County supplies trucks) Grade-All work per hour (County supplies trucks) with sod Swale Work per foot dig only (Contractor supplies trucks) Swale work per foot with sod (Contractor supplies trucks)		
Location: See map - East Eldorado Lake Dr		
Section: <u>18</u> Town: <u>27</u> Range: <u>33</u> Se	egment No: <u>3-6480-01</u>	
Digging total length linear feet: 2,200 ft, of which 750 ft is double dig Sod Estimate Sq Ft: 32,000 Type of sod: Bahia Estimated Hours: Start Date: Completion date: Notes:		
Mark start and stop area with paint on road	l.	
County Representative		Date

Request Details Report

Request Number Associated Work Order Observed Date/Time MA3-11913-R OSC-3291-WO 4/8/14 1:07:P Citizen Information Name Phone (352) 978-3274 Ext. Andy Whittaker **Alternate Phone** Address **Email Address** East Eldorado Lake Dr (6480)Organization Requestor Contact Issue and Location **Property Damage** Issue Activity Map Page SEC TWN RNG **OSC Swale Restoration** Address Number Route East Eldorado Lake Dr (6480) Intersect Route Details Citizen reports that mowers destroyed the survey markers on his property and his neighbor's. He wants for us to have them replaced. Notes History 4/8/2014 Markers will be replaced. Dean, Randy Lee, Steven 4/14/2014 Contract swale work requested. 5/30/2014 Modified contract swale request. Lee, Steven Resolution _____

Time Arrived_____

Time Departed_____

Request Response Date 04/08/2014

