



To:	From: Pu	iblic Works/Road (<u>Ops</u>
Fax:	Pages:	1	
Phone:	Date:	12/21/2017	
E-Mail:			
TREE REMOVAL REQUE	<u>ST</u>		
Road Name: Dixie Ave Segme Nearest City:Fruitland Park Address: 501 S. Dixie Ave., F Section 09 Township: 19 Description of Tree: Oak Tree Location of Tree: In front of 50 Size of tree (s): 32 Inches Grind Stump? Reg If trim what class? Class 1 Power Lines or other hazards i Sod? Yes No	ruitland Park Range: 24 01 S. Dixie Ave move Stump? Class 2 nvolved? Yes	<u>e.</u> Class 3 <u></u>	
Comments:Tree has been mar	ked with oran	<u>ge tape.</u>	
Questions concerning tree size(s) shall be or designee prior to the performance of paid in accordance with the terms and or below.	the work. Any wor	rk performed without agree	ment by all parties shall be
Approved by: County Represer	<u>Date:</u> ntative		
Work Completed and OK t	to Bayı Ves	No	
Inspected by:	u ray: 1es [No Date:	
Invoice #		Date:	
LITVICE T		· · · · · · · · · · · · · · · · · · ·	

Request Details Report

Request Number MA1-12446-R	Associated Work Order	Observed Date/Time 12/21/17 1:30:P	
Citizen Information Name Address	Phone Alternate Email Ad	S INDIGUENCE	-
Organization Requestor Lake Count Contact Donnie Gar			
Issue and Location	Issue	Tree Removal	
Activity TRE Removal	Map F	age SEC TWN	RNG
Address Number 5(01		
Route Dixie Av (5507)			
Intersect Route Details There is a dead tree in fro fall at any point.	nt of address that is a hazard. It is lea	ning towards the house and	could possibly
Notes			
History			
Resolution			
Request Response Date	12/21/2017		
Time Departed_			





FOR INTERNAL USE ONLY

N129-19-24

