

То:	From: Public Works/Road Ops	
Fax:	Pages:	1
Phone:	Date:	9/19/2017
E-Mail:		
TREE REMOVAL REQUEST	Γ	
or designee prior to the performance of the	Range: 28  mp? no Class 2  olved? Yes  Type of so flagging tape  ddressed and agre work. Any work p	Class 3 ☐ No⊠
Approved by:  County Representat	Date:	
County Representative		
Work Completed and OK to I	Pay: Yes	No
Inspected by:		Date:
Invoice #		

## Request Details Report

**Request Number Associated Work Order Observed Date/Time** MA3-16013-R 9/18/17 10:05:A Citizen Information Name Michael Suver Phone Ext. **Alternate Phone** Address 732 Email Address mikesuv12@gmail.co Dora Av (4554) Tavares FL Organization Requestor Contact **Issue and Location** Issue Tree Removal **Activity** Map Page SEC TWN RNG Address Number 732 Route Dora Av (4554) Intersect Route **Details** CARL Request # W004924-091617 - "There is a large oak tree in front of my house in the right of way that is being eaten by carpenter ants. The middle is getting pretty rotted out and I am concerned that the tree may become a danger and topple over in a storm if it gets completely eaten. I am also finding the ants in my house and they may be coming from the tree. Can you please remove the tree before it becomes a danger?" Notes History Resolution \_\_\_\_\_

Request Response Date

Time Arrived\_\_\_\_\_


Time Departed\_\_\_\_\_

Date









(1-888-461-3625)