



LAKE COUNTY
FLORIDA

To: _____ From: **Public Works/Road Ops**

Fax: _____ Pages: **1**

Phone: _____ Date: **10/11/2017**

E-Mail: _____

TREE REMOVAL REQUEST

Road Name: Lake Eustis Dr Segment No.: _____

Nearest City: Leesburg

Address: 11442 Lake Eustis Dr., Leesburg, FL 34788

Section 24 Township: 19 Range: 25

Description of Tree: Pine Tree

Location of Tree: In front of address 11442 Lake Eustis Dr. Leesburg, FL 34788

Size of tree (s): 21"

Grind Stump? _____ Remove Stump? _____

If trim what class? Class 1 Class 2 Class 3

Power Lines or other hazards involved? Yes No

Sod? Yes No Type of sod Needed: N/A

Comments: _____

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Approved by: _____ Date: _____

D.G. County Representative

Work Completed and OK to Pay: Yes <input type="checkbox"/> No <input type="checkbox"/>	
Inspected by: _____	Date: _____
Invoice # _____	

Request Details Report

Request Number

MA1-12253-R

Associated Work Order

Observed Date/Time

10/6/17 11:25:A

Citizen Information

Name William Wilson

Phone (352) 308-9424 **Ext.**

Address 11442
Lake Eustis Dr (4851)
Leesburg FL

Alternate Phone

Email Address

Organization

Requestor

Contact

Issue and Location

Activity

TRE Removal

Issue

Tree Removal

Map Page

SEC TWN RNG

Address Number 11442

Route Lake Eustis Dr (4851)

Intersect Route

Details

Mr. Wilson reported that there is a dead pine tree in front of his address that is may start to drop dead limbs. He wants to see if someone can come out and take a look at the tree to see if it can be removed before it becomes a real hazard.

Notes

History

10/6/2017 Mr. Wilson was made aware that his request for the Supervisor for further investigaiton. nbautista

Resolution _____

Request Response Date 10/06/2017 _____

Date _____

Time Arrived _____

Time Departed _____



1180821

11441

1180546

1184568

11442 Lake Eustis Dr.

Pine tree to be removed.

11423
1496543

LAKE EUSTIS DR

2507489

1143

1496683
11442

1184312

11504

11514

1184398

11526

1184622

11415

11422

1684692

3886397

11418

1496659

11538

1301394


11416

1496641

96560



SEE SHEET NO. 2E/13B



This is a general representation of recorded public RW found in the records of the Right of Way Department. It is not a search of all public records. Should any discrepancy exist between the RW shown on this map and the corresponding recorded document, the recorded document will prevail. A survey may be required to physically establish the location of any RW on the ground.

FOR INTERNAL USE ONLY