

Native Land and Tree, Inc.

9422 Number Two Road Howey In The Hills, FL 34737

Invoice

Date	Invoice #
9/22/2014	3067

Bill To

Lake County Public Works / Road Operation Road Operations Center PO Box 7800 Tavares, FL 32778-7800 SEP 2 2 2014 2 2 2014

ROAD OPERATIONS

Project

Tree Removal

Description	Quantity	Rate	Amount
Removal of 61+ " DBH Oak tree with stump ground out, located at 3520 Griffin Ave Lady Lake	1	4,100.00	4,100.00
0			
OK TO PAY - NATIVE LAND & TREE			
(Tree Removal) PO#: 20140347 Acct#: 5053200.830460 Goods Recd:			

Thank you for your business.

Total

\$4,100.00

Payments/Credits

\$0.00

Phone #	Fax#	E-mail
352-266-7970	N/A	Davidnlt23@gmail.com

1/2 1/2 9/2014 0/34/14 BP 9/24/14



To: Native Land and Tree F	rom: Public Works/	Road Ops
Fax: 352-330-1600 P	ages: 1	
Phone: 352-266-7970	Date:	9/24/2014
E-Mail: buffy@nativelandandtro	ee.com	
TREE REMOVAL REQUEST		
Description of Tree: oak Location of Tree: in front of address Size of tree (s): 60" inch Grind Stump: yes Remove Stump: If trim what class: Class 1 Class Power Lines or other hazards involve	ange: 24 listed above no ass 2 Class 3 C	
Comments: Tree is marked with flag		
Questions concerning tree size(s) shall be addree Supervisor or the Senior Contracting Officer prion agreement by all parties shall be paid in accorda should be sent to the address listed below.	r to the performance of the w	ork. Any work performed without
Approved by County Representative	: Robert Baker Date:8	<u>3-14-2014</u>
Work completed and OK to Pay: Yes	⊠ No □	
Inspected by: Robert Baker date:	9-23-2014	
Invoice #: 3067		

Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.

Mailing Address, PO Box 7800, Tavares Florida 32778,
Phone Number: 352-343-6439 – Fax Number: 352-742-3888

Revised: 6-29-2012




To:	From: Pu	<u>blic Works/Road Ops</u>
Fax:	Pages:	1
Phone:	Date:	8/14/2014
E-Mail:	erled with a state of the state	
TREE REMOVAL REQUE	ST	
the 90% curve. Size of tree (s): 60 inches Grind Stump? yes Remove St If trim what class? Class 1 Power Lines or other hazards in Sod? Yes No	Range: 24 Tree Idress 3520 Gr tump? Class 2 nvolved? Yes Type of s	Class 3 \Box No No Noeded; No No Noeded;
or designee prior to the performance of the	e addressed and ag he work. Any work	ge tape. greed upon in writing by either the Project Manager k performed without agreement by all parties shall be ntract. Invoices should be sent to the address listed
Approved by: County Represent	Date:	·
Work Completed and OK to	o Pay: Yes	No_
Inspected by: Invoice #		Date:


Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.

Mailing Address, PO Box 7800, Tavares Florida 32778,
Phone Number: 352-343-6439 – Fax Number: 352-742-3888













RIGHT-OF ENTRY STATEMENT

Date: 08/08/2	2014
Property Owner's Name	e:Tom Nash
Tenant's Name:	CHRIS HURST
Address of Property:	3520 Griffin Av (7807)
City/Zip Code:	Lady Lake, FL 32159
Description of Work:	Removal of Oak Tree
Right of Entry	
property. I freely grant	owner, or an owner's authorized representative of the above described, and without coercion, the right of access and entry to said property for ag work that exists in the County right-of-way and on my property.
	nes, septic tanks, water lines, utilities located on the described property to
Print Name:	THOMAS WAYNE (ASX)
Signature;	Show Onl

Request Details Report

Request Number **Associated Work Order Observed Date/Time** MA1-9078-R 8/5/14 8:51:A Citizen Information Name Tom Nash Phone (352) 750-0584 Alternate Phone (305) 219-3363 Address 3516 Email Address Palmetto COH a sprail Cem Griffin Av (7807) Lady Lake Florida Organization Requestor Contact Issue and Location Issue Tree Trimming Activity Map Page SEC TWN RNG TRE Trimming Address Number 3520 Route Griffin Av (7807) Intersect Route **Details** Per Email: Good Morning Sir, I own the property at 3520 Griffin Ave in Lady Lake. There is a rather large Oak tree on the West side of my home that is causing several issues to my property and to the quality of life for my tenant. There are limbs as low as 5 foot off the ground can't safely mow any longer. There are very large limbs literally inches from my roof shedding excessive amounts of leaves which is causing rot and mildew. My electrical service line is also a potential candidate for being pulled down as well. The tree was hit by lightning you can see the path and the discharge site at the base. This tree has the potential to cause catastrophic damage to my home. I would like for someone to come out and evaluate it and have it pruned for safety. Thank You, Notes History 8/5/2014 Request was printed and handed to Supervisor for further nbautista investigation. 8/8/14; Right of Enlay was sent to me. wash via limbil of a copy was sent via fax. Resolution _ Request Response Date 08/06/2014 Date

Time Arrived ____
Time Departed ____