



Native Land and Tree, Inc.
9422 Number Two Road
Howey In The Hills, FL 34737

Invoice

Date	Invoice #
4/20/2015	3089

Bill To
Lake County Public Works / Road Operation Road Operations Center PO Box 7800 Tavares, FL 32778-7800

Handwritten notes:
MAY 07 2015
LAK...

Description	Quantity	Rate	Project
			Tree Removal
			Amount
Removal of a 21" and 23" DBH Oak tree with stumps ground out located at 18200 Ravenswood Road, Altoona	2	1,050.00	2,100.00
Removal of a 21" DBH Hickory tree with stumps ground out located at 3613 Cactus Lane, Mt. Dora	1	1,050.00	1,050.00
<p><i>Handwritten signature:</i> JK 5/8/15</p> <hr/> <p>OK TO PAY NATIVE LAND & TREE PO#: 20150065 Acct#: 1120.5053200.830460 Goods Recd: <u>4 1 20 12015</u></p>			
Thank you for your business.			Total <u>\$3,150.00</u>
			Payments/Credits \$0.00

Handwritten note: 2015-7-15

Phone #	Fax #	E-mail
352-266-7970	N/A	Davidnlt23@gmail.com

Handwritten notes:
JK 5/8/15
BP 5/7/15



LAKE COUNTY
FLORIDA

To: Native Land and Tree From: Public Works/Road Ops

Fax: 352-330-1600 Pages: 1

Phone: 352-266-7970 Date: 5/7/2015

E-Mail: buffy@nativelandandtree.com

TREE REMOVAL REQUEST

Road Name: Cactus Lane Segment #: 3-4061-02

Nearest City: Mt. Dora

Address: 3613 Cactus Ln.

Section: 35 Township: 19 Range: 26

Description of Tree: hickory

Location of Tree: address listed above

Size of tree (s): 21" inch

Grind Stump: yes Remove Stump: no

If trim what class: Class 1 Class 2 Class 3

Power Lines or other hazards involved: Yes No

Sod: Yes No Type of sod Needed: NONE

Comments: tree marked with flagging tape

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Maintenance Area Supervisor or the Senior Contracting Officer prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Approved by County Representative : Robert Baker Date:4-8-2015

Work completed and OK to Pay: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Inspected by: Robert Baker date: 4-22-2015
Invoice #: 3089

Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.
Mailing Address, PO Box 7800, Tavares Florida 32778,
Phone Number: 352-343-6439 – Fax Number: 352-742-3888



LAKE COUNTY
FLORIDA

To: _____ From: **Public Works/Road Ops**

Fax: _____ Pages: **1**

Phone: _____ Date: **4/7/2015**

E-Mail: _____

TREE REMOVAL REQUEST

Road Name: Cactus Ln Segment No.: 3-4061-02

Nearest City: Mount Dora

Address: 3613

Section 35 Township: 19 Range: 26

Description of Tree: Hickory

Location of Tree: in Right-of-Way

Size of tree (s): 21"

Grind Stump? yes Remove Stump? _____

If trim what class? Class 1 Class 2 Class 3

Power Lines or other hazards involved? Yes No

Sod? Yes No Type of sod Needed: _____

Comments: Tree is marked with flagging tape.

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

S.W. Approved by: _____ Date: _____
County Representative

Work Completed and OK to Pay: Yes <input type="checkbox"/> No <input type="checkbox"/>	
Inspected by: _____	Date: _____
Invoice # _____	

BP
4/8/15

Request Details Report

Request Number
MA3-13207-R

Associated Work Order

Observed Date/Time
4/7/15 8:38:A

Citizen Information

Name Brenda Collier
Address 3613
Cactus Ln (4061)
Mount Dora FL

Phone (352) 455-3763 Ext.
Alternate Phone
Email Address

Organization

Requestor
Contact

Issue and Location

Activity

Issue Tree Removal
Map Page SEC TWN RNG

Address Number 3613

Route Cactus Ln (4061)

Intersect Route

Details

Citizen reports a dead tree in the ROW.

Notes

History

4/7/2015 Contract tree removal requested.

Lee, Steven

Resolution _____

Request Response Date _____

Date _____

Time Arrived _____

Time Departed _____









To: Native Land and Tree From: Public Works/Road Ops

Fax: 352-330-1600 Pages: 1

Phone: 352-266-7970 Date: 5/7/2015

E-Mail: buffy@nativelandandtree.com

TREE REMOVAL REQUEST

Road Name: Ravenswood Road Segment #: 3-8872-01

Nearest City: Altoona

Address: 18200 Ravenswood Rd.

Section: 19 Township: 17 Range: 27

Description of Tree: Two (2) oak trees

Location of Tree: address listed above

Size of tree (s): 21" and 23" inches

Grind Stump: yes Remove Stump: no

If trim what class: Class 1 Class 2 Class 3

Power Lines or other hazards involved: Yes No

Sod: Yes No Type of sod Needed: none

Comments: trees are marked with flagging tape

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Maintenance Area Supervisor or the Senior Contracting Officer prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

Approved by County Representative : Robert Baker Date:4-8-2015

<u>Work completed and OK to Pay: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>
<u>Inspected by: Robert Baker date: 4-22-2015</u>
<u>Invoice #: 3089</u>

Lake County Road Operations, Public Works 12901 County Landfill Road, Tavares.
Mailing Address, PO Box 7800, Tavares Florida 32778,
Phone Number: 352-343-6439 – Fax Number: 352-742-3888



LAKE COUNTY
FLORIDA

To: _____ From: **Public Works/Road Ops**

Fax: _____ Pages: **1**

Phone: _____ Date: **4/8/2015**

E-Mail: _____

TREE REMOVAL REQUEST

Road Name: Ravenswood Rd Segment No.: 3-8872-01

Nearest City: Altoona

Address: 18200

Section 19 Township: 17 Range: 27

Description of Tree: two oak trees

Location of Tree: in Right-of-Way

Size of tree (s): one 21", one 23"

Grind Stump? yes Remove Stump? _____

If trim what class? Class 1 Class 2 Class 3

Power Lines or other hazards involved? Yes No

Sod? Yes No Type of sod Needed: _____

Comments: trees marked with flagging tape

Questions concerning tree size(s) shall be addressed and agreed upon in writing by either the Project Manager or designee prior to the performance of the work. Any work performed without agreement by all parties shall be paid in accordance with the terms and conditions of the Contract. Invoices should be sent to the address listed below.

5.4 Approved by: _____ Date: _____
County Representative

Work Completed and OK to Pay: Yes <input type="checkbox"/> No <input type="checkbox"/>	
Inspected by: _____	Date: _____
Invoice # _____	

BP
4/8/15

Request Details Report

Request Number
MA3-13210-R

Associated Work Order

Observed Date/Time
4/7/15 10:00:A

Citizen Information

Name Bob Cline

Phone (352) 669-0978 Ext.

Address 18200
Ravenswood Rd (8872)
Altoona FL

Alternate Phone (407) 474-6290

Email Address

Organization

Requestor

Contact

Issue and Location

Activity

Issue

Tree Removal

Map Page

SEC TWN RNG

Address Number 18200

Route Ravenswood Rd (8872)

Intersect Route

Details

Citizen reports that several trees in the ROW are dead or dying. Several branches have fallen and damaged his fence.

Notes

History

5'6" = 21"
6" = 23"
Two Oak trees
Grind stump
No trim

Resolution _____

Request Response Date _____

Date _____

Time Arrived _____

Time Departed _____





